



CE-ATA Technical Errata

Errata ID	Protocol 010
Affected Spec Ver.	Protocol 1.0
Corrected Spec Ver.	

Submission info

Name	Company	Date
Amber Huffman	Intel	07/20/2005

Description of the specification technical flaw (add space as needed)

The definition table in the Timing Requirements section has an incorrect definition for CRC16. CRC16 is 16-bits in MMC, not 15-bits as currently marked. The erratum corrects this error.

Description of the correction

The definitions table in the Timing Requirements section, section 3, shall be modified as shown:

CRC16	CRC check bits (15-bit 16-bit)
-------	--

Disposition log

07/20/2005	Erratum captured
08/31/2005	Erratum ratified

Technical input submitted to the CE-ATA Workgroup is subject to the terms of the CE-ATA contributor's agreement.